

DESCRIPTION

• Highlights: -Helps protect the welding filter from welding sparks and spatter -Replacement part -For use with 3M™ Speedglas™ Welding Helmets and Filters -Outer Protection Plate 3M[™] Speedglas[™] Outside Protection Plates are designed for use with 3M[™] Speedglas[™] Welding Helmets and Filters and protect the welding filter from sparks and spatter. 3M™ Speedglas™ Outside Protection Plates are a replacement part designed to be used when the original has been damaged or worn out. Help protect your welding ONE SIZE - ONE SIZE filter from sparks and spatter by ensuring that your Outside Protection Plate is functioning properly.



SIZE AVAILABILITY

Specifications/Technical Data	
Brand	3M
Compatible Welding Helmet	9100 Series
Part Type	Consumable
Product series	9100 MP, 9100 MP-Lite, 9100, Speedglas 9100 Air, 9100 FX, 9100 FX- Air
Product Type	Outside Protection Plate
Recommended application	Welding, Metal Processing, Metal Repair, Grinding